

79mm/3.11in



44.8mm/1.76in



153mm/6.20in

MODE FUNCTION SWITCH

Long press MODE until the screen value blinks, single press MODE to switch the mode to °C&°F, press 1 key to adjust the unit

Celsius-°C unit



Fahrenheit-°F unit



HIGH PRECISION SENSOR

High quality upgraded sensor, professional high and low temperature measurement, anti-interference / acceptance / higher stability





Indicator light

VA reverse display screen

Backlight/upshift

Mode switch

Red line switch/
Downshift

Switch/
temperature trigger

Battery installation



Battery model:
1.5V AAA*2

VA HD BACKLIGHT

In a dark environment, turn on the infrared laser/backlight bright screen

